



AUDI A4: 1GHT328

Vinnumber:	WAUZZZ8K4EA090596	Versionname:	A4 BER TDie 136PK
First Registrationdate:	11/02/2014	Fiscalpower:	
Expertise Mileage:	129750	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4813
Maintenance:	BINNEN 22800KM		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	CD Rear parking sensors
GPS storage	
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 967,00

Floor covering F L, Tear, E - Replace 252,00



Bumper corner R R, Scratch(es), Acceptable

0,00



Door R L, Bump(s), Acceptable 0,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim F R, Scratch(es), Acceptable 0,00



Engine protective plate, Hole, E - Replace 50,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door F R, Scratch(es), Acceptable 0,00



Rocker panel inner R R, Scratch(es), Acceptable 0,00



Door R R, Scratch(es), Acceptable 0,00

Door R R, Scratch(es), Acceptable 0,00



Interior, Dirty, Cleaning 50,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Bump(s), Acceptable 0,00

