



AUDI A3 BERLINE: JA8760

| | | | |
|-------------------------|--------------------------|--------------|--|
| Vinnnumber: | WAUZZZ8V7F1106107 | Versionname: | 1.6 TDI ULTRA 81KW ATTRACTION |
| First Registrationdate: | 4/03/2015 | Fiscalpower: | |
| Expertise Mileage: | 123743 | Power Kw: | 81 |
| Bodytype: | | Body color | Light Grey |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Battery functioning | Yes | Parking lot | 4611 |
| Number of doors | 4 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |

Options

| | | |
|--------------------------------|------------------------------|--------------------------|
| Radio CD | Central consol F | |
| Windows electric F | Rear parking sensors | |
| Windows electric R | Type of Tow bar | Tow bar removable |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Xenon | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear


| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/55/16/91 V LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 7 mm | Fr.R. | Michelin: 7 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | |
|------------|------------|
| Compressor | Yes |
| Jack | Yes |

| | |
|---|---------------|
| Total cost ex VAT | 301,68 |
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Tailgate, Scratch(es), LI - Repair and paint (complete) | 301,68 |





| | |
|--|------|
| Alloy rim R L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display