



AUDI A6: 1EZG381

Vinnnumber:	WAUZZZ4G4DN137943	Versionname:	A6 AVANT Multitr.177PK Aut.
First Registrationdate:	26/04/2013	Fiscalpower:	
Expertise Mileage:	85712	Power Kw:	130
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4201
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Seats electric F L	
Windows electric F	Seats electric F R	
Windows electric R	Sun Roof electric	
Cruise Control	Central consol F	
Steering wheel multifunctional	Luggage cover	
Seats F heated	Front parking sensors	
Radio multimedia	Rear parking sensors	
Type of headlighting	Type of Tow bar	Tow bar fixed
Type of GPS	Headlighting Halogen	
Type of Lining	GPS big screen color	
Type of climate control	Lining leather	
	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	812,93
-------------------	--------


Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09
---	--------



Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00

