


AUDI A5: 1FH0851

Vinnumber:	WAUZZZ8T0EA005732	Versionname:	A5 COUPE Quattro S-line S-tr.224PK Aut.
First Registrationdate:	1/07/2013	Fiscalpower:	
Expertise Mileage:	211645	Power Kw:	165
Bodytype:	Coupé	Body color:	.
Gearbox:	Automatic	Body color:	Grey
Transmission:	4 Weel	Paint type:	Metalic
Fueltype:	Petrol	Rims summer:	Aluminium
Battery functioning:	Yes	Oil level:	OK
Number of doors:	2	Parking lot:	4309
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Central consol F
Windows electric F		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather and alcantara	
Type of climate control	Manual climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/40/18/97 V LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3393,12
-------------------	---------

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	360,21
---	--------



Sill outer L, Scratch(es), LI - Repair and paint (complete)	372,60
---	--------



Bumper moulding R, Broken, E - Replace	17,28
--	-------



Front bumper, Bump(s) and scratch(es), Le - Replace and paint	862,80
---	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	264,21
---	--------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Tailgate, Scratch(es), LI - Repair and paint (complete)	362,02
---	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 369,84



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Door F R, Bump(s), Acceptable 0,00

