



BMW 3: 1GPB202

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnnumber: | WBA3Y11010D376156 | Versionname: | 3 GRAN TURISMO 318dA |
| First Registrationdate: | 21/03/2014 | Fiscalpower: | 136PK Aut. |
| Expertise Mileage: | 73758 | Power Kw: | 100 |
| Bodytype: | Hatchback | Body color: | Silver |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3611 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|----------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Rear parking sensors |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Seats F heated | |
| Radio multimedia | |
| Type of headlighting: | Headlighting Xenon |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining artificial leather |
| Type of climate control: | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 225/50/18/95 W LightMetal | | | | |
| Summer tyres: | Fr.L. | Continental: 3 mm | Fr.R. | Continental: 3 mm |
| | Re.L. | Continental: 4 mm | Re.R. | Continental: 4 mm |

Assistance equipment

| | |
|--|--------|
| Total cost ex VAT | 367,80 |
| Roof pillar L, Bump(s), PDR - Knock out without painting | 82,80 |

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00





Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Internal Boot Lining R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00

