



## CITROEN C4 Picasso: 1GEH229

Vinnnumber:	<b>VF73E9HC8DJ874686</b>	Versionname:	<b>GR.C4 PICASSO Exclusive</b>
First Registrationdate:	<b>15/01/2014</b>	Fiscalpower:	<b>ETG 115PK Aut.</b>
Expertise Mileage:	<b>173194</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

## Options

Radio CD		Seats electric F L
GPS storage		Seats electric F R
GPS storage	<b>HD</b>	Panoramic roof
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Seats F heated		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/50/17/93 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Other: 6 mm</b>	Fr.R.	<b>Other: 6 mm</b>
	Re.L.	<b>Other: 7 mm</b>	Re.R.	<b>Other: 7 mm</b>

## Assistance equipment

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	2750,85
-------------------	---------

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------

		Alloy rim R L polished, Damaged, E - Replace 235,20
		
	Alloy rim R R polished, Scratch(es), E - Replace 235,20	
		
		Alloy rim F R polished, Scratch(es), Acceptable 0,00 <i>No pictures to display</i>
Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 356,20		
		
Rearview mirror R complete, Scratch(es), LI - Repair and paint (complete) 100,00		
		
Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80		
		
	Door frame R R, Scratch(es), Acceptable 0,00 <i>No pictures to display</i>	
Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35		
		
Alloy rim F L polished, Damaged, E - Replace 235,20		



Door seal R R, Damaged, P - Check 0,00



Door panel R R, Damaged, E - Replace 114,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20

