



BMW X1: 1FEK048			
Vinnnumber:	WBAVY11030VW89194	Versionname:	X1 sDrive16 116PK
First Registrationdate:	6/06/2013	Fiscalpower:	
Expertise Mileage:	98613	Power Kw:	85
Bodytype:	SUV	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1121
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/17/94 H Steel			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment	
Compressor	Yes

Total cost ex VAT	2427,32
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20



Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Smart repair 110,64



Reflector, Damaged, E - Replace 20,00



Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Scratch(es), It - Spot repair 0,00



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Wheel cover F L, Damaged, E - Replace 30,00





Bumper R, Scratch(es), Smart repair 110,64



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Floor covering F L, Damaged, E - Replace 252,00



Front bumper, Scratch(es), Smart repair 110,64



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35





Front bumper, Scratch(es), Acceptable

0,00

No pictures to display