


BMW 3: 1EQW581

Vinnnumber:	WBA3K91090F929317	Versionname:	3 TOURING 316d 116PK
First Registrationdate:	26/02/2013	Fiscalpower:	
Expertise Mileage:	187970	Power Kw:	85
Bodytype:	Break	Body color:	Brown
Gearbox:	MAN 6 VIT	Body color:	.
Transmission:	Back	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Battery functioning:	Yes	Oil level:	OK
Number of doors:	5	Parking lot:	3210
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Manual climate control	
Level control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H Steel			
Winter tyres:	Fr.L.	Kleber: 6 mm	Fr.R.	Kleber: 6 mm
	Re.L.	Kleber: 6 mm	Re.R.	Kleber: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	359,40
Sill outer L, Scratch(es), LI - Repair and paint (complete)	248,40



Door R L, Bump(s), Acceptable	0,00
-------------------------------	------



Wheel cover F R, Scratch(es), E - Replace 24,00



Door R R, Bump(s), Acceptable 0,00



Front bumper, Scratch(es), Acceptable 0,00



Wing R L, Bump(s), Acceptable 0,00



Wheel cover F L, Scratch(es), Acceptable 0,00



Door F R, Bump(s), PDR - Knock out without painting 63,00



Wheel cover R R, Scratch(es), E - Replace 24,00

