


BMW 3: 1GKF775

Vinnumber:	WBA3D11080F328928	Versionname:	3 BER 318d 136PK
First Registrationdate:	3/03/2014	Fiscalpower:	
Expertise Mileage:	132948	Power Kw:	100
Bodytype:	Berline	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3404
Maintenance:	IN 27000 KM		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Front parking sensors
GPS storage	HD
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/94 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Runflat **Yes**

Total cost ex VAT **401,80**

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) **95,00**



Door F R, Bump(s) and scratch(es), Acceptable **0,00**

No pictures to display

Door R L, Scratch(es), Acceptable **0,00**

No pictures to display

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

