


BMW 3: 1FTZ362

Vinnnumber:	WBA3D91050J219581	Versionname:	3 BER 316dA 116PK Aut.
First Registrationdate:	24/10/2013	Fiscalpower:	
Expertise Mileage:	188758	Power Kw:	85
Bodytype:	Berline	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4704
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 H Steel				
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

 Compressor **Yes**

 Total cost ex VAT **1082,45**

 Wheel cover R R, Missing, E - Replace **30,00**

 Tailgate, Chemical polution, Acceptable **0,00**

No pictures to display

 Wheel cover F R, Scratch(es), Acceptable **0,00**

No pictures to display


 Front bumper, Scratch(es), LI - Repair and paint (complete) **211,80**



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Sill outer L, Scratch(es), LI - Repair and paint (complete) 310,50



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bump(s), LI - Repair and paint (complete) 318,35

