


**BMW 3: 1FXW346**

Vinnumber:	<b>WBA3K91010F932017</b>	Versionname:	<b>3 TOURING 316d 116PK</b>
First Registrationdate:	<b>2/12/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>187897</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4622</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar removable</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/50/17/94 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

**Assistance equipment**

 Runflat **Yes**

 Total cost ex VAT **636,28**

 Rearview mirror housing R, Scratch(es), Smart repair **110,64**


Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

**95,00**

	Windscreen, Stone chip(s), Windscreen repair	0,00
	Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
		
	Rearview mirror housing L, Scratch(es), Smart repair	110,64
		
	Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Engine protective plate, Hole, E - Replace	35,00
		
	Door seal R, Worn, Acceptable	0,00
		
	Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
		
	Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
		

