



BMW 3: 1GUW954

Vinnumber:	WBA3Y11040D449696	Versionname:	3 GRAN TURISMO 318d
First Registrationdate:	7/05/2014	Fiscalpower:	143PK
Expertise Mileage:	132426	Power Kw:	105
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3433
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining artificial leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear





	225/50/16/95 W LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Total cost ex VAT	1010,28
Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	301,68



Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
	
Alloy rim F R, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
