


FORD Galaxy: 1FCC837

Vinnnumber:	WF0MXXGBWMDP26193	Versionname:	GALAXY Ghia DPF 136PK
First Registrationdate:	22/05/2013	Fiscalpower:	
Expertise Mileage:	139796	Power Kw:	100
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3814
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 V LightMetal				
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 3 mm	Re.R.	Uniroyal: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------














Total cost ex VAT	915,87
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Bump(s), PDR - Knock out without painting	63,00



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door F L, Bump(s) and scratch(es), L L - Repair and paint (complete)	382,02
--	---------------

			
			
Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)			360,21
			
			
Bumper R, Bump(s) and scratch(es), Smart repair			110,64
			
Front bumper, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			