


**AUDI A4: 1JEU321**

Vinnnumber:	<b>WAUZZZ8K8FA054458</b>	Versionname:	<b>A4 AVANT Ultra 136PK</b>
First Registrationdate:	<b>27/11/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>168181</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4631</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting:	<b>Headlighting Xenon</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining leather</b>		
Type of climate control:	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/92 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>
-----------------------	------------

Total cost ex VAT	925,64
-------------------	--------

Wing R L, Chemical polution, LI - Repair and paint (complete)	308,20
---	--------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Rear spoiler, Chemical polution, LI - Repair and paint (complete)	115,56
---	--------



Interior, Dirty, Cleaning

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08

