



## CITRO?N C5: 1HAT538

Vinnnumber:	<b>VF7RD9HLOEL508195</b>	Versionname:	<b>C5 BER Business GPS</b>
First Registrationdate:	<b>5/06/2014</b>	Fiscalpower:	<b>113PK</b>
Expertise Mileage:	<b>152448</b>	Power Kw:	<b>84</b>
Bodytype:		Body color	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3621</b>
Number of doors	<b>4</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

## Options

Radio CD		Central consol F
GPS storage	<b>HD</b>	Rear parking sensors
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>225/60/16/98 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT 372,12

Steering wheel, Worn, P - Check 0,00



Rocker panel inner R L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper R, Bump(s), 11 - Repair and paint (complete) 307,80



Floor covering F L, Burned, Smart repair	64,32
--	-------



Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Dashboard, Scratch(es), Acceptable	0,00
------------------------------------	------

*No pictures to display*

Rocker panel inner F L, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*