



FORD Transit 350L: 894APP			
Vinnumber:	WF0NXXTFN9M77471	Versionname:	TRANSIT CH2C 350L LWB
First Registrationdate:	4/06/2009	Fiscalpower:	115pk
Expertise Mileage:	77069	Power Kw:	85
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV06
Number of doors:	4		
Number of seats:	6		
Number head rests:	6		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options		
Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	NOT OK
		Wiperblades	OK

Degree of wear				
	215/75/16/113 R Steel			
Summer tyres:	Fr.L.	Toyo: 9 mm	Fr.R.	Toyo: 9 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment	
Spare wheel	Yes
Total cost ex VAT	3914,51
Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	165,13



Seat cover F R, Damaged, E - Replace	300,00
--------------------------------------	--------



Wheel cover R L, Missing, E - Replace	22,50
---------------------------------------	-------



Wheel cover F R, Missing, E - Replace 22,50



Tailgate, Damaged, Le - Replace and paint 433,50



Windscreen, Damaged, E - Replace 395,40



Wheel cover F L, Missing, E - Replace 22,50



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Door moulding Lower F L, Missing, E - Replace 91,50



Front bumper, Strained , Smart repair 110,64



Sill outer L, Rust, LI - Repair and paint (complete) 232,88



Door moulding Lower R R, Missing, E - Replace 91,50



Rearview mirror L complete, Damaged, E - Replace 138,00



Headlight R, Damaged, E - Replace 321,00



Interior, Dirty, Cleaning 150,00



Sidewall RL (LCV), Damaged, E - Replace 80,00



Wheel cover R R, Missing, E - Replace 22,50



Sill outer R, Rust, LI - Repair and paint (complete) 232,88



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Bonnet, Bump(s), LI - Repair and paint (complete)	217,56
---	--------



Floor covering F R, Damaged, E - Replace	237,00
--	--------

