


BMW X3: 1GW1560

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------|
| Vinnumber: | WBAWY110100C58535 | Versionname: | X3 sDrive18 136PK |
| First Registrationdate: | 19/05/2014 | Fiscalpower: | |
| Expertise Mileage: | 145815 | Power Kw: | 100 |
| Bodytype: | SUV | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3525 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Sun Roof electric |
| Windows electric F | Panoramic roof |
| Windows electric R | Central consol F |
| Cruise Control | Luggage cover |
| Steering wheel multifunctional | Front parking sensors |
| Radio multimedia | Rear parking sensors |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|---------------------|-------|---------------------|
| | 225/60/17/99 V LightMetal | | | |
| Summer tyres: | Fr.L. | Dunlop: 6 mm | Fr.R. | Dunlop: 6 mm |
| | Re.L. | Dunlop: 5 mm | Re.R. | Dunlop: 5 mm |

Assistance equipment

| | | | |
|------------------------------------|------------|------------|---------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 150,00 |
| Ignition key, Missing, E - Replace | | | 150,00 |
| <i>No pictures to display</i> | | | |
| Door R L, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Windscreen, Repaired, Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Bonnet, Stone chip(s), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |

No pictures to display