



#### AUDI A4: 1GS113

Vinnnumber:	<b>WAUZZZ8K0EA136098</b>	Versionname:	<b>A4 AVANT TDi 120PK</b>
First Registrationdate:	<b>15/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>205408</b>	Power Kw:	<b>88</b>
Bodytype:	<b>Break</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2231</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

#### Options

Radio CD		Central consol F
GPS storage	<b>DVD</b>	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining semi-leather</b>	
Type of climate control	<b>Autom climate control</b>	
Sport seats		

#### Limited Technical Inspection


Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

#### Degree of wear

	<b>245/40/18/97 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 6 mm</b>	Fr.R.	<b>Goodyear: 6 mm</b>
	Re.L.	<b>Uniroyal: 8 mm</b>	Re.R.	<b>Uniroyal: 8 mm</b>

#### Assistance equipment

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>75,00</b>
Bonnet, Stone chip(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Roof, Stone chip(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Rear window, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Windscreen, Bad repair, E - Replace			<b>0,00</b>



Door R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Front bumper, Scratch(es), Acceptable 0,00

*No pictures to display*

Interior, Stain, Cleaning 75,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

*No pictures to display*