


**FORD Mondeo: 1FDD309**

Vinnumber:	<b>WF0EXXGBBBDP26509</b>	Versionname:	<b>MONDEO BER Econetic Trend 115PK</b>
First Registrationdate:	<b>29/05/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>66027</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4213</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/55/16/93 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 2 mm</b>	Fr.R.	<b>Michelin: 2 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	911,50
-------------------	--------


Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display


Wing R R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Rear spoiler, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------

