



AUDI A4: 1HUB013

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnnumber: | WAUZZZ8K8FA024036 | Versionname: | A4 AVANT Ultra 136PK |
| First Registrationdate: | 2/10/2014 | Fiscalpower: | |
| Expertise Mileage: | 109157 | Power Kw: | 100 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 4506 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| GPS storage | Luggage cover |
| GPS storage | CD |
| Windows electric F | Rear parking sensors |
| Windows electric R | Type of Tow bar |
| Cruise Control | Tow bar removable |
| Steering wheel multifunctional | |
| Seats F heated | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/60/16/92 V LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|-------------------|------|
| Total cost ex VAT | 0,00 |
|-------------------|------|

| | |
|-------------------------------------|------|
| Door frame R R, Bump(s), Acceptable | 0,00 |
|-------------------------------------|------|

No pictures to display

| | |
|--|------|
| Windscreen, Stone chip(s), E - Replace | 0,00 |
|--|------|



| | |
|--|------|
| Alloy rim R L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display