


OPEL Astra: 1FRI276

Vinnnumber:	W0LPD6EW1EG010083	Versionname:	ASTRA BER ecoFL.Enjoy
First Registrationdate:	1/10/2013	Fiscalpower:	Active St/St 110PK
Expertise Mileage:	181042	Power Kw:	81
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	1704
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Luggage cover	
GPS storage		SD	Rear parking sensors
GPS storage			
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/95 V Steel				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	617,36
-------------------	--------

Sunblind L, Broken, E - Replace	10,00
---------------------------------	-------




Wheel cover F R, Scratch(es), Acceptable	0,00
------------------------------------------	------



Ignition key, Missing, E - Replace 150,00



Wing R L, Bump(s) and scratch(es), Acceptable 0,00



Bumper spoiler F, Damaged, E - Replace 42,00



Tailgate, Bump(s), PDR - Knock out without painting 63,00



Roof pillar R, Bump(s), Acceptable 0,00



Door panel F L, Scratch(es), Acceptable 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00



Door R L, Bump(s), Acceptable 0,00

No pictures to display

Bumper R, Repaired, P - Check 0,00



Wing F R, Bump(s), LI - Repair and paint (complete) 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Rear window, Not original part, Remove lettering 25,00



Windscreen, Crack, E - Replace 0,00



Wing R R, Bump(s) and scratch(es), It - Spot repair 115,56



Door panel F R, Scratch(es), Acceptable 0,00

