



MERCEDES CLA: 1FNJ645			
Vinnumber:	WDD1173011N026355	Versionname:	CLA BER 200 CDI 136PK
First Registrationdate:	28/08/2013	Fiscalpower:	
Expertise Mileage:	127603	Power Kw:	100
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3410
Maintenance	SERVICE B3 IN 345D		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	1		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Options			
Radio CD		Central consol F	
GPS storage	HD		
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Manual climate control		
Sport seats			
Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK
Degree of wear			
Summer tyres:	225/45/17/91 Y LightMetal		
	Fr.L.	Vredestein: 6 mm	Fr.R.
			Vredestein: 5 mm
	Re.L.	Yokohama: 4 mm	Re.R.
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1450,20
Wing R L, Scratch(es), LI - Repair and paint (complete)			308,20
Windscreen, Stone chip(s), E - Replace			487,20



GPS disc, Missing, Acceptable	0,00
-------------------------------	------



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Backrest cover F L, Worn, Acceptable	0,00
--------------------------------------	------

No pictures to display

Interior, Worn, Acceptable	0,00
----------------------------	------



Seat cover F L, Worn, Acceptable	0,00
----------------------------------	------

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------




GPS, No damage, Acceptable	0,00
----------------------------	------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door F L, Bump(s), PDR - Knock out without painting	63,00
---	-------



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------

