


MERCEDES A: 1JHT485

Vinnumber:	WDD1760081V046658	Versionname:	2.1 A 200 CDI STYLE
First Registrationdate:	23/12/2014	Fiscalpower:	
Expertise Mileage:	65951	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1614
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1351,65
-------------------	----------------

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------





Interior, Dirty, Cleaning 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Ignition key, Missing, E - Replace 150,00

No pictures to display

Front bumper, Scratch(es), Acceptable 0,00

No pictures to display


Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door R L, Scratch(es), Acceptable 0,00

No pictures to display