



<b>NISSAN Qashqai: MA5433</b>			
Vinnumber:	<b>SJNFDNJ11U1194695</b>	Versionname:	<b>QASHQAI 4WD Tekna 130PK</b>
First Registrationdate:	<b>1/01/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>132151</b>	Power Kw:	<b>96</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4514</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>	
Radio CD	Seats electric F L
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	<b>Headlighting LED</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>225/45/19/96 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 3 mm</b>	Fr.R.	<b>Continental: 3 mm</b>
	Re.L.	<b>Pirelli: 6 mm</b>	Re.R.	<b>Pirelli: 6 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>636,70</b>
Wing F L, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)			<b>318,35</b>





Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---------------------------------------------------------------------	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*