



OPEL Astra: 1FCT156			
Vinnnumber:	W0LPD8EW3D8050699	Versionname:	ASTRA BRE ecoFL.Enjoy Active St/St 110PK
First Registrationdate:	27/05/2013	Fiscalpower:	
Expertise Mileage:	135339	Power Kw:	81
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4308
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/17/94 Y Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT		961,76	
Door R R, Scratch(es), Acceptable		0,00	
<i>No pictures to display</i>			
Door panel F R, Worn, Acceptable		0,00	
<i>No pictures to display</i>			
Door panel F L, Worn, Acceptable		0,00	
<i>No pictures to display</i>			
Door F R, Scratch(es), Acceptable		0,00	
<i>No pictures to display</i>			
Rear window, Scratch(es), E - Replace		370,00	





Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 301,68



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display