



**OPEL Insignia: 1HBT758**

|                                    |                          |              |   |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber:                         | <b>WOLGM8ER9E1137172</b> | Versionname: | <b>INSIGNIA BRE ecoFLEX Edition 120PK</b> |
| First Registrationdate:            | <b>13/06/2014</b>        | Fiscalpower: |   |
| Expertise Mileage:                 | <b>183076</b>            | Power Kw:    | <b>88</b>                                 |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Dark Brown</b>                         |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                            |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>                          |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                 |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>1204</b>                               |
| Number of doors:                   | <b>5</b>                 |              |   |
| Number of seats:                   | <b>5</b>                 |              |   |
| Number head rests:                 | <b>5</b>                 |              |   |
| Rims summer:                       | <b>Aluminium</b>         |              |   |
| Category:                          | <b>Passenger Car</b>     |              |   |
| Oil level:                         | <b>OK</b>                |              |   |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |   |

**Options**

|                                |                              |                          |
|--------------------------------|------------------------------|--------------------------|
| Windows electric F             | Central consol F             |                          |
| Windows electric R             | Luggage cover                |                          |
| Cruise Control                 | Front parking sensors        |                          |
| Steering wheel multifunctional | Rear parking sensors         |                          |
| Radio multimedia               | Type of Tow bar              | <b>Tow bar removable</b> |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                          |
| Type of Lining                 | <b>Lining fabrics</b>        |                          |
| Type of climate control        | <b>Autom climate control</b> |                          |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>215/60/16/95 V LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|               | Re.L.                            | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 565,40 |
|-------------------|--------|

|                                     |        |
|-------------------------------------|--------|
| Alloy rim R R, Damaged, E - Replace | 235,20 |
|-------------------------------------|--------|



|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                     |        |
|-------------------------------------|--------|
| Alloy rim R L, Damaged, E - Replace | 235,20 |
|-------------------------------------|--------|

Alloy rim R L, Damage(s), L - Replace 200,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display