



MERCEDES C: 1JPN683

Vinnnumber:	WDD2052371F150857	Versionname:	C BRE 200 BlueTEC 136PK
First Registrationdate:	2/02/2015	Fiscalpower:	
Expertise Mileage:	66455	Power Kw:	100
Bodytype:		Body color	Silver
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	B3 DANS 47 JOURS	Parking lot	4327
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	225/50/17/94 W LightMetal			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			535,08
Internal Boot Lining L, Damaged, Acceptable			0,00
No pictures to display			
Internal Boot Lining R, Damaged, Acceptable			0,00
No pictures to display			
Rocker panel inner F L, Bump(s), Acceptable			0,00
No pictures to display			
Door F L, Scratch(es), Acceptable			0,00
No pictures to display			
Ignition key, Missing, E - Replace			150,00
No pictures to display			
Bumper F R, Scratch(es), Acceptable			0,00
No pictures to display			

Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	290,08
---	--------



Rocker panel inner R L, Bump(s), Acceptable	0,00
---	------

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------

