


MERCEDES A: 1GEE104

Vinnumber:	WDD1760121J235096	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	14/01/2014	Fiscalpower:	
Expertise Mileage:	125059	Power Kw:	80
Bodytype:		Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4124
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 Y LightMetal			
Summer tyres:	Fr.L.	Barum: 5 mm	Fr.R.	Barum: 5 mm
	Re.L.	Barum: 8 mm	Re.R.	Barum: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	859,76
-------------------	---------------

GPS disc, Missing, E - Replace	0,00
--------------------------------	-------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Accident, E - Replace 499,20



Ignition key, Missing, E - Replace 150,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Door frame R L, Scratch(es), It - Spot repair 115,56

