



**OPEL Corsa: 1FCJ152**

Vinnnumber:	<b>W0L0SDL68D4189334</b>	Versionname:	<b>CORSA BER ecoFL Enjoy Active DPF 95PK</b>
First Registrationdate:	<b>23/05/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>106525</b>	Power Kw:	<b>70</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4716</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Luggage cover
GPS storage	
GPS storage	<b>HD</b>
Windows electric F	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/65/15/88 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 8 mm</b>	Fr.R.	<b>Uniroyal: 8 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>1006,50</b>
-------------------	----------------

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Door frame R R, Scratch(es), It - Spot repair	<b>115,56</b>
---	---------------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Front bumper, Scratch(es), LI - Repair and paint (complete)

169,44



Door R R, Scratch(es), 67 - Polish

55,19



Door frame R L, Scratch(es), It - Spot repair

115,56



Bumper R, Scratch(es), 67 - Polish

55,19



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

