



OPEL Astra: 1FAY515

Vinnnumber:	W0LPD8EW2D8049060	Versionname:	ASTRA BRE ecoFL Enjoy Active St/St 110PK
First Registrationdate:	13/05/2013	Fiscalpower:	
Expertise Mileage:	56340	Power Kw:	81
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1527
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H Steel			
Summer tyres:	Fr.L.	Firestone: 7 mm	Fr.R.	Firestone: 7 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Emergency spare wheel	Yes
-----------------------	------------

Total cost ex VAT	643,78
-------------------	--------

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof pillar L, Bump(s), LI - Repair and paint (complete) 220,18



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Scratch(es), LI - Repair and paint (complete) 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00

