




| RENAULT Scenic: 1HAX550            |                          |              |                                 |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnnumber:                        | <b>VF1JZ14K650895055</b> | Versionname: | <b>SCENIC Energy Life 110PK</b> |
| First Registrationdate:            | <b>6/06/2014</b>         | Fiscalpower: |                                 |
| Expertise Mileage:                 | <b>157458</b>            | Power Kw:    | <b>81</b>                       |
| Bodytype:                          | <b>Hatchback</b>         | Body color:  | <b>Silver</b>                   |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                  |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Steel</b>                    |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                       |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3812</b>                     |
| Number of doors:                   | <b>5</b>                 |              |                                 |
| Number of seats:                   | <b>5</b>                 |              |                                 |
| Number head rests:                 | <b>5</b>                 |              |                                 |
| Rims summer:                       | <b>Steel</b>             |              |                                 |
| Category:                          | <b>Passenger Car</b>     |              |                                 |
| Oil level:                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                 |

| Options                        |                               |
|--------------------------------|-------------------------------|
| Radio CD                       | Central consol F              |
| Windows electric F             | Luggage cover                 |
| Windows electric R             |                               |
| Cruise Control                 |                               |
| Steering wheel multifunctional |                               |
| Radio multimedia               |                               |
| Type of headlighting           | <b>Headlighting Halogen</b>   |
| Type of GPS                    | <b>GPS big screen color</b>   |
| Type of Lining                 | <b>Lining fabrics</b>         |
| Type of climate control        | <b>Manual climate control</b> |

| Limited Technical Inspection |           |                     |            |
|------------------------------|-----------|---------------------|------------|
| Airco functioning            | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile           | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime          | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                 | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                    | <b>OK</b> | Transmission        | <b>OK</b>  |
|                              |           | Lighting            | <b>OK</b>  |
|                              |           | Wiperblades         | <b>OK</b>  |

| Degree of wear |                             |                       |       |                       |
|----------------|-----------------------------|-----------------------|-------|-----------------------|
|                | <b>205/60/16/92 H Steel</b> |                       |       |                       |
| Summer tyres:  | Fr.L.                       | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|                | Re.L.                       | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

| Assistance equipment  |            |      |            |
|---|------------|------|------------|
| Emergency spare wheel                                       | <b>Yes</b> | Jack | <b>Yes</b> |
| Total cost ex VAT   |            |      | 271,80     |
| Front bumper, Scratch(es), LI - Repair and paint (complete) |            |      | 211,80     |



|                                       |       |
|---------------------------------------|-------|
| Wheel cover R R, Missing, E - Replace | 30,00 |
|---------------------------------------|-------|



|                                       |       |
|---------------------------------------|-------|
| Wheel cover F R, Damaged, E - Replace | 30,00 |
|---------------------------------------|-------|



|  |      |
|--|------|
| Wheel cover F L, Scratch(es), Acceptable | 0,00 |
|--|------|

*No pictures to display*

|                                   |      |
|-----------------------------------|------|
| Door R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*