


RENAULT Grand Scenic: 1FE0816

Vinnumber:	VF1JZ14M649061052	Versionname:	Bose Ed.5pl.110PK
First Registrationdate:	7/06/2013	Fiscalpower:	
Expertise Mileage:	136132	Power Kw:	81
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	GEEN MELDING	Parking lot:	3825
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/95 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	95,00
-------------------	-------

Alloy rim R L polished, Damaged, Acceptable	0,00
---	------

No pictures to display

Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim R R polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Seat cover F L, Damaged, Acceptable	0,00
-------------------------------------	------



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00

