



RENAULT Master 35 L3H1: 1GDN906			
Vinnnumber:	VF1MAF4SE50077078	Versionname:	MASTER 35 B/F L3H2 Gr.conf.(E5)125PK
First Registrationdate:	8/01/2014	Fiscalpower:	
Expertise Mileage:	142991	Power Kw:	92
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV11
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/65/16/112 R Steel			
Summer tyres:	Fr.L.	Kleber: 7 mm	Fr.R.	Kleber: 7 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment	
Total cost ex VAT	529,71
Wing R R, Bump(s), LI - Repair and paint (complete)	231,15



Rearview mirror housing L, Crack, Acceptable	0,00
<i>No pictures to display</i>	
Rearlight R , Damaged, E - Replace	91,50



Interior, Dirty, Cleaning	0,00
---------------------------	------



Sill outer L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Steering wheel, Worn, Acceptable 0,00



Rearlight L, Damaged, E - Replace 91,50



Sidewall RR (LCV), Bump(s) and scratch(es), It - Spot repair 115,56

