



RENAULT Master 35 L2H2: 1GXC096			
Vinnnumber:	<b>VF1MAFESC50570082</b>	Versionname:	<b>MASTER 35 B/F L2H2 Gr.Conf.(E5) 125PK</b>
First Registrationdate:	<b>23/05/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>131586</b>	Power Kw:	<b>92</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV03</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options			
Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Radio multimedia		Type of Tow bar	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>225/65/16/112 R Steel</b>			
Summer tyres:	Fr.L.	<b>Fulda: 4 mm</b>	Fr.R.	<b>Fulda: 4 mm</b>
	Re.L.	<b>Fulda: 8 mm</b>	Re.R.	<b>Fulda: 8 mm</b>

Assistance equipment	
Total cost ex VAT	1011,53
Trunk door R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Damaged, E - Replace	104,00



Interior, Dirty, Cleaning	50,00
---------------------------	-------





Wing trim R R, Scratch(es), E - Replace 69,00



Wheel cover R R, Missing, E - Replace 22,50



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Wheel cover F R, Missing, E - Replace 22,50



Wheel cover F L, Missing, E - Replace 22,50



Sill outer L, Scratch(es), LI - Repair and paint (complete) 232,88



Protection plate M, Tear, E - Replace 74,00



Door moulding Lower R R, Scratch(es), E - Replace 91,50



Wing trim R R, Scratch(es), E - Replace 69,00



Roof, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R L, Missing, E - Replace	22,50

