



RENAULT Clio: 1DXY106

Vinnnumber:	VF1KR2H4H47787320	Versionname:	CLIO BRE TomTom LIVE
First Registrationdate:	1/10/2012	Fiscalpower:	FAP 104g 89PK
Expertise Mileage:	82843	Power Kw:	65
Bodytype:	Break	Body color:	Beige
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4823
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Radio multimedia	Luggage cover
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/88 H Steel			
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Total cost ex VAT	433,44
Wheel cover F R, Damaged, E - Replace	24,00



Wing R R, Bad repair, Acceptable	0,00
----------------------------------	------



Front bumper, Scratch(es), LI - Repair and paint (complete)	169,44
---	--------



Wheel cover R R, Scratch(es), E - Replace 24,00



Bonnet, Bad repair, Acceptable 0,00



Luggage space cover, Damaged, E - Replace 192,00



Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace 24,00



Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Ceiling, Scratch(es), Acceptable 0,00

No pictures to display