



RENAULT CAPTUR: 1JSU876

Vinnnumber:	VF12RFL1H52343252	Versionname:	1.5 DCI 90 ENERGY INTENS ECO2
First Registrationdate:	17/02/2015	Fiscalpower:	
Expertise Mileage:	116253	Power Kw:	66
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4730
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	Tow bar fixed
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/95 V LightMetal			
Winter tyres:	Fr.L.	Kleber: 7 mm	Fr.R.	Kleber: 7 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	312,00
-------------------	---------------

Door R R, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Interior, Dirty, Cleaning	0,00
---------------------------	-------------



Bonnet, Hail damage, PDB, Hail	0,00
--------------------------------	-------------

Door(s), Hail damage, PDR - Hail 0,00



Roof, Hail damage, PDR - Hail 0,00



Seat cover R L, Hole, E - Replace 312,00



Bumper R, Bump(s), Acceptable 0,00

No pictures to display