



**RENAULT KANGOO EXPRESS COMPACT: 1KKA502**

Vinnnumber:	<b>VF1FW17F553115315</b>	Versionname:	<b>1.5DCI 75 COMPACT CONFORT</b>
First Registrationdate:	<b>18/05/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>248870</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>NOT OK</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>NOT OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning:	<b>NOT OK</b>	Battery functioning:	<b>Yes</b>
Tires wear profile:	<b>NOT OK</b>	Power steering:	<b>No</b>
Idle position:	<b>NOT OK</b>	Sound engine:	<b>NOT OK</b>
Engine startingtime:	<b>NOT OK</b>	Clutch test:	<b>NOT OK</b>
Exhaust gass:	<b>NOT OK</b>	Wiper fluid level:	<b>NOT OK</b>
Handbrake:	<b>NOT OK</b>	Transmission:	<b>NOT OK</b>
		Lighting:	<b>NOT OK</b>
		Wiperblades:	<b>NOT OK</b>

**Degree of wear**

	<b>185/70/14/88 T Steel</b>			
Summer tyres:	Fr.L.	<b>Firestone: 1,5 mm</b>	Fr.R.	<b>Firestone: 1,5 mm</b>
	Re.L.	<b>Firestone: 6 mm</b>	Re.R.	<b>Firestone: 6 mm</b>

**Assistance equipment**

Spare wheel:	<b>Yes</b>	Jack:	<b>Yes</b>
--------------	------------	-------	------------

Total cost ex VAT	1086,25
Front bumper, Damaged, E - Replace	398,40



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	231,15
---	--------



Tyre F R, Damaged, E - Replace

105,00



Steel rim R L, Damaged, E - Replace

72,60



Rearview mirror housing L, Missing, E - Replace

35,00



Steel rim F R, Damaged, E - Replace

72,60



Reflector, Damaged, E - Replace

20,00



Wing R L, Scratch(es), Acceptable

0,00

*No pictures to display*

Window handle F L, Damaged, E - Replace

25,00



Rearlight L, Damaged, E - Replace

91,50



Rearview mirror housing R, Missing, E - Replace

35,00



Bodywork, Not original part, Acceptable

0,00

