



RENAULT MASTER: 1LHE992

Vinnnumber:	VF1MAF4ZE53694827	Versionname:	2.3 DCI 120KW ENERGY GR CONFORT L3H2 35
First Registrationdate:	29/09/2015	Fiscalpower:	
Expertise Mileage:	108606	Power Kw:	120
Bodytype:	Transporter	Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	LCV17
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		SD
GPS storage		
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/65/16/112 R Steel			
Summer tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	940,82
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Gear shift lever cover, Damaged, E - Replace	9,00



Sill outer R, Bump(s) and scratch(es), It - Spot repair	187,56
---	--------



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Wheel aperture R R, Damaged, LI - Repair and paint (complete) 246,00



Floor covering F L, Hole, E - Replace 237,00



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Wheel cover F R, Damaged, E - Replace 22,50

