



RENAULT Master 35 L2H2: 1ANY888

Vinnnumber:	VF1MAFEEC44518994	Versionname:	MASTER 35 B/F L2H2 Gr.Conf.145PK
First Registrationdate:	17/02/2011	Fiscalpower:	
Expertise Mileage:	123456789	Power Kw:	107
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	NOT OK
Battery functioning:	No		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	NOT OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
Windows electric F		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining artificial leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	NOT OK	Battery functioning	No
Tires wear profile	NOT OK	Power steering	No
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	NOT OK	Clutch test	NOT OK
Exhaust gass	NOT OK	Wiper fluid level	NOT OK
Handbrake	NOT OK	Transmission	NOT OK
		Lighting	NOT OK
		Wiperblades	NOT OK

Degree of wear

	225/65/16/112 R Steel			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Spare wheel	No	Jack	No
-------------	-----------	------	-----------

Total cost ex VAT 1079,86

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Wheel cover R R, Missing, E - Replace 22,50



Bumper corner R R, Scratch(es), Smart repair 110,64



Supplementary brake lights, Damaged, E - Replace 33,00



Wing trim R R, Scratch(es), Smart repair 110,64



Jack, Missing, E - Replace 42,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair 0,00



Wing trim R R, Scratch(es), Smart repair 110,64



Bodywork, Not original part, Acceptable 0,00



Seat cover F L, Tear, Repair/replace (lump sum) 0,00



Door moulding Lower F R, Scratch(es), Smart repair 110,64



Bumper moulding R Mid, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Damaged, E - Replace 22,50



Grill, Missing, E - Replace 10,00



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Wheel cover F L, Missing, E - Replace 22,50



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Missing, E - Replace 22,50



Fuel tank stopper, Scratch(es), Paint 0,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display