


SKODA Octavia: 1HAU136

Vinnumber:	TMBJG7NE1E0229341	Versionname:	OCTAVIA COMBI Ambition
First Registrationdate:	5/06/2014	Fiscalpower:	105PK
Expertise Mileage:	197316	Power Kw:	77
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3726
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V Steel			
Summer tyres:	Fr.L.	Michelin: 1,5 mm	Fr.R.	Michelin: 1,5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1577,66
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Accident, LI - Repair and paint (complete)	0,00





Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door frame R L, Bump(s), It - Spot repair 0,00



Reflector, Broken, E - Replace 0,00



Wing R R, Bump(s), PDR - Knock out without painting 111,00



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Door F L, Bump(s) and scratch(es), It - Spot repair 0,00



Door F L, Accident, LI - Repair and paint (complete) 0,00



Tailgate, Accident, Le - Replace and paint 1034,68



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Accident, Le - Replace and paint

0,00



Door R L, Accident, Le - Replace and paint

0,00



Windscreen, Broken, E - Replace

0,00

