


**SKODA OCTAVIA COMBI: 1KKV228**

|                                    |                          |              |  |
|------------------------------------|--------------------------|--------------|--|
| Vinnnumber:                        | <b>TMBJK7NE3F0235240</b> | Versionname: | <b>2.0 CRTDI 135KW DSG 6 GREENTEC RS</b> |
| First Registrationdate:            | <b>22/05/2015</b>        | Fiscalpower: |  |
| Expertise Mileage:                 | <b>154579</b>            | Power Kw:    | <b>135</b>                               |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Black</b>                             |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>                           |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>                         |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4725</b>                              |
| Number of doors:                   | <b>5</b>                 |              |  |
| Number of seats:                   | <b>5</b>                 |              |  |
| Number head rests:                 | <b>5</b>                 |              |  |
| Rims summer:                       | <b>Aluminium</b>         |              |  |
| Category:                          | <b>Passenger Car</b>     |              |  |
| Oil level:                         | <b>OK</b>                |              |  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |  |

**Options**

|                                |                              |                          |
|--------------------------------|------------------------------|--------------------------|
| Radio CD                       | Central consol F             |                          |
| Windows electric F             | Luggage cover                |                          |
| Windows electric R             | Rear parking sensors         |                          |
| Cruise Control                 | Type of Tow bar              | <b>Tow bar removable</b> |
| Steering wheel multifunctional |                              |                          |
| Seats F heated                 |                              |                          |
| Radio multimedia               |                              |                          |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                          |
| Type of Lining                 | <b>Lining leather</b>        |                          |
| Type of climate control        | <b>Autom climate control</b> |                          |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

| 225/40/18/92 V LightMetal |       |                |       |                |
|---------------------------|-------|----------------|-------|----------------|
| Summer tyres:             | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
|                           | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

**Assistance equipment**

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

|   |         |
|---|---------|
| Total cost ex VAT   | 1360,80 |
| Door R R, Scratch(es), Acceptable                                     | 0,00    |
| <i>No pictures to display</i>   |         |
| Ignition key, Missing, E - Replace                                    | 150,00  |
| <i>No pictures to display</i>   |         |
| Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) | 95,00   |





Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Bump(s) and scratch(es), Le - Replace and paint 651,00



Door R L, Bump(s), PDR - Knock out without painting 63,00

