


**KIA Sportage: 1GVB807**

Vinnnumber:	<b>U5YPC815AEL492984</b>	Versionname:	<b>SPORTAGE 2WD Sense</b>
First Registrationdate:	<b>8/05/2014</b>	Fiscalpower:	<b>115PK</b>
Expertise Mileage:	<b>117203</b>	Power Kw:	<b>85</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1119</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Xenon</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining semi-artificial leather</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>235/55/18/100 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	926,78
-------------------	--------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*


Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Door R L, Bump(s) and scratch(es), Acceptable 0,00

*No pictures to display*

Alloy Rims (all), Rust, Acceptable 0,00

*No pictures to display*