



VOLVO V40: 1FDU784			
Vinnumber:	YV1MV5151D2060101	Versionname:	V40 D3 Base 150PK
First Registrationdate:	3/06/2013	Fiscalpower:	
Expertise Mileage:	147617	Power Kw:	110
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	UITVOEREN	Parking lot:	4315
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics

Limited Technical Inspection			
Airco functioning:	OK	Battery functioning:	Yes
Tires wear profile:	OK	Power steering:	Yes
Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Wiper fluid level:	OK
Handbrake:	OK	Transmission:	OK
		Lighting:	OK
		Wiperblades:	OK

Degree of wear			
Summer tyres:	205/55/16/91 H LightMetal		
	Fr.L.	Fr.R.	Michelin: 4 mm
	Re.L.	Re.R.	Continental: 7 mm

Assistance equipment			
Repair kit:	Yes	Compressor:	Yes
Total cost ex VAT			568,92
Front bumper, Scratch(es), It - Spot repair			115,56




Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
--	---------------






Door R L, Bump(s), PDR - Knock out without painting 63,00



Door frame R R, Bump(s) and scratch(es), It - Spot repair 115,56





Door F L, Bump(s), PDR - Knock out without painting 63,00



Door panel F L, Worn, Acceptable 0,00



Rear window, Scratch(es), E - Replace 0,00



Maintenance, Maintenance, Execute 0,00

