



VOLKSWAGEN Caddy: 1JEE665

Vinnumber:	WV2ZZZ2KZFX058390	Versionname:	CADDY MAXI LIFE Trendl.102PK OMBOUW Dub.
First Registrationdate:	24/11/2014	Fiscalpower:	
Expertise Mileage:	155382	Power Kw:	75
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4214
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/94 H Steel			
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Total cost ex VAT	784,42
Wing R R, Scratch(es), 67 - Polish	0,00



Bonnet, Scratch(es), 67 - Polish	0,00
----------------------------------	-------------



Tailgate, Bump(s), LI - Repair and paint (complete)	410,02
---	---------------



Interior, Damaged, Acceptable 0,00



Wheel cover F R, Damaged, E - Replace 22,50



Bumper R, Broken, E - Replace 329,40



Bodywork, Damaged, Acceptable 0,00



Wheel cover F L, Damaged, E - Replace 22,50

