


VOLKSWAGEN TIGUAN: 1FBP115

Vinnnumber:	WVGZZZ5NZDW099107	Versionname:	TIGUAN Trend&Fun BM Tech.110PK
First Registrationdate:	16/05/2013	Fiscalpower:	
Expertise Mileage:	168282	Power Kw:	81
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4609
Maintenance	PLUS 12800 KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/65/16/98 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	297,36
-------------------	--------

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------



Bumper Trim F, Scratch(es), Smart repair	110,64
--	--------



Ceiling, Damaged, Smart repair 64,32




Front bumper, Scratch(es), Acceptable 0,00



Door F R, Bump(s) and scratch(es), Acceptable 0,00



Bonnet, Bump(s), Acceptable 0,00



Roof pillar L, Bump(s), PDR - Knock out without painting 122,40



Windscreen, Repaired, P - Check 0,00



Rearview mirror glass L, Scratch(es), Acceptable 0,00



Door R R, Bump(s) and scratch(es), Acceptable 0,00



Door R L, Scratch(es), Acceptable 0,00

