



**VOLKSWAGEN Caddy: 1HBD857**

Vinnnumber:	<b>WV2ZZZ2KZEX151417</b>	Versionname:	<b>CADDY MAXI LIFE</b>
First Registrationdate:	<b>10/06/2014</b>	Versionname:	<b>Basel.BM OMBOUW 2Cab.</b>
Expertise Mileage:	<b>126051</b>	Fiscalpower:	<b>10</b>
Bodytype:	<b>Transporter</b>	Power Kw:	<b>75</b>
Gearbox:	<b>MAN 5 VIT</b>	Body color	<b>Dark Grey</b>
Transmission:	<b>Front</b>	Paint type	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer	<b>Steel</b>
Battery functioning	<b>Yes</b>	Oil level	<b>OK</b>
Number of doors	<b>5</b>	Parking lot	<b>3628</b>
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Light Commercial Vehicle</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD	
Cruise Control	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining artificial leather</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 T Steel</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT 1470,05

Sidewall RR (LCV), Scratch(es), It - Spot repair 115,56



Side window R L, Scratch(es), E - Replace 0,00



Bumper R, Damaged, E - Replace 329,40




Sidewall RL (LCV), Bump(s), It - Spot repair 115,56



Front bumper, Bump(s), E - Replace 398,40



Roof, Chemical polution, LI - Repair and paint (complete) 361,13



Bonnet, Scratch(es), Acceptable 0,00

*No pictures to display*

Sliding door R, Scratch(es), Acceptable 0,00

*No pictures to display*

Ignition key, Missing, E - Replace 150,00

*No pictures to display*