



VOLVO V60: 1GWN841			
Vinnnumber:	<b>YV1FW8481E1211966</b>	Versionname:	<b>V60 BRE D2 Kinetic 115PK</b>
First Registrationdate:	<b>20/05/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>125713</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4114</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	<b>Tow bar removable</b>
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>205/60/15/96 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 3 mm</b>	Fr.R.	<b>Goodyear: 3 mm</b>
	Re.L.	<b>Goodyear: 4 mm</b>	Re.R.	<b>Goodyear: 4 mm</b>

Assistance equipment	
Repair kit	<b>Yes</b>
Compressor	<b>Yes</b>
Total cost ex VAT	<b>211,80</b>
Tailgate, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Windscreen, Stone chip(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>

