



VOLKSWAGEN Caddy: 1JEE661

Vinnnumber:	WV2ZZZ2KZFX055198	Versionname:	CADDY MAXI LIFE Trendl.102PK OMBOUW Dub.
First Registrationdate:	24/11/2014	Fiscalpower:	
Expertise Mileage:	195256	Power Kw:	75
Bodytype:	Transporter	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	4704
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Rear parking sensors
Windows electric F	Type of Tow bar Tow bar fixed
Cruise Control	
Type of headlighting Headlighting Halogen	
Type of Lining Lining fabrics	
Type of climate control Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/94 H Steel			
Winter tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT **860,67**

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) **231,15**



Sliding door R, Bump(s), PDR - Knock out without painting **111,00**



Bumper corner R L, Incomplete, E - Replace **49,00**



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Engine protective plate, Missing, E - Replace 85,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Acceptable 0,00

No pictures to display

Wheel cover F R, Broken, E - Replace 22,50



Maintenance, Maintenance, Execute 0,00

No pictures to display

Door F R, Bump(s), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, No damage, Acceptable 0,00

No pictures to display