



**VOLKSWAGEN Caddy: 1JEE670**

Vinnnumber:	<b>WV2ZZZ2KZFX055160</b>	Versionname:	<b>CADDY MAXI LIFE Trendl.102PK OMBOUW Dub.</b>
First Registrationdate:	<b>24/11/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>169902</b>	Power Kw:	<b>75</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2413</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/94 H Steel</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 4 mm</b>	Fr.R.	<b>Goodyear: 4 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT **1663,82**

Maintenance book, Missing, E - Replace **0,00**



Front bumper, Bump(s) and scratch(es), E - Replace **398,40**





Supplementary brake lights, Broken, E - Replace 33,00



Door R L, Bump(s), PDR - Knock out without painting 63,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 279,15



Bumper grille F L, Scratch(es), E - Replace 30,30



Wheel cover F R, Missing, E - Replace 22,50



Boot cover, Broken, E - Replace 37,50



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 458,02



Door R R, Scratch(es), LI - Repair and paint (complete) 286,76



Door F R, Scratch(es), 67 - Polish 55,19

