



VOLVO V40: 1FQM221

Vinnumber:	YV1MV8481E2103301	Versionname:	V40 D2 Base 115PK
First Registrationdate:	24/09/2013	Fiscalpower:	
Expertise Mileage:	122421	Power Kw:	84
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4310
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 0 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------


Total cost ex VAT	532,56
Front bumper, Scratch(es), It - Spot repair	115,56



Floor covering F L, Hole, E - Replace	252,00
---------------------------------------	---------------



Wing R L, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Mirror side blinker L, Damaged, E - Replace 30,00



Vanity mirror, Damaged, E - Replace 72,00

